

Approved by TECNAM under DOA privileges EASA.21J.335 03rd February 2010

Page. 1 of 1

NOTE: *Only engineering aspects are ENAC approved. If inspection, modifications or technical prescriptions and their relative times of compliance are compulsory for ENAC, the sanction is in the relevant airworthiness directives.*

INFORMATION **RECOMMENDED** **MANDATORY**

SUBJECT: MTOW increase to 600Kg for P2002-JF aircraft.

SCOPE: To apply the change of the MTOW it is necessary to request the following KIT from Tecnam:

- 1) New airspeed indicator instrument;
- 2) New edition of Aircraft Flight Manual;
- 3) New placard of maneuvering speed;

MODELS AFFECTED: P2002-JF, all s/n

TIME OF COMPLIANCE: At Customer's choice

MANPOWER: 1.0 man-hour

REQUIRED MATERIAL: KIT n° SB010

TOOLING: Nil

WEIGHT AND BALANCE Nil

REFERENCES: Nil

PUBLICATIONS AFFECTED: Doc. N° 2002/28 "P2002-JF Flight Manual"

INSTRUCTIONS Uninstall the airspeed indicator and send it to Tecnam; then Tecnam will provide you with the KIT n° SB010.

For further information, please contact Tecnam at:

Tel 0039 0823 622899

Fax 0039 0823 620134

E-mail m.oliva@tecnam.org or r.insero@tecnam.com